



Ccr critical capacitor

C1 too small

C2 ok

if  $\alpha$  is too big the generator doesn't work  $\tan \alpha = 1 / C \cdot \omega$

with  $\omega = 2 \pi \text{ frot}$