


## GENERAL ARRANGEMENT OF RADIATOR



THINING OF TUBE IN BOTTOM 1 FEET  
WHICH CAUSED PUNCTURE

