


SHEAR DIAGRAM CALCULATIONS

$FE_y + FD_y + FC_y + FB_y = 0$
 $-903.760\# + 1109.71\# - 1007.50\# + 801.554\# = 0$

205.95#



MOMENT CALCULATIONS

[illegible]